

## Thundering Surf

**Distributor:** Air-Tech Systems – NJ, NY, PA  
Office: 732-244-0295  
Cell: 732-581-6956

**Customer:** Thundering Surf  
Beach Haven, NJ

**Applicator:** Owner



### Problem:

- High iron particle content in city water had a staining effect on the concrete pool. The owner felt it necessary to empty, acid wash and fill the pool many times during the short summer season for best performance.
- Constant acid washing provided more and more surface area for particles to settle into and discolor the pool.

### Solution:

- Prior to opening for the summer season, the pool was again pressure washed, acid washed and the pool coated with CeRam-Kote 99P pool paint.

### Result:

- Because the pool surface is now smooth, the iron particles have no place to settle, the pool stays brilliant white and requires only normal maintenance.